Tuesday	, February	28, 2023		
Tuesday, Fel	oruary 28, 2023	Ballroom A	Ballroom B	Ballroom C
8:00 AM	10:00 AM	Room Monitor: Nick Marx Contact: nick@irml.ca /403.318.5010	Room Monitor: Jose Arenas Contact: jose.arenas@vysusgroup.com /403.461.1632	Room Monitor: Doug Brett Contact: dbrett@secure-energy.com / 403 510 2658
9:00 AM	10:00 AM		KEYNOTE SPEAKER Dr. Alan Murray "Dealing with Profound Change"	
10:00 AM	10:30 AM		Coffee Break	
10:00 AM	10:30 AM	STUDENT POSTER - all day, located between Moose Nook/Beavert  Jolene Borrelli		
		Investigation of QW-403.6 Minimum Base Metal Thickness Requirements for Carbon and Low Alloy Steels		
		Ballroom A	Ballroom B	Ballroom C
		Asset Integrity Management	Failure Case Study	Regulatory/Codes
10:15 AM	12:00 PM	Room Monitor: Trent Tarleton Contact: trent.tarleton@interpipeline.com / 403.612.4850	Room Monitor: Cody Scheu Contact: Cody.scheu@cnrl.com / 403.816.7218	Room Monitor: Doug Brett Contact: dbrett@secure-energy.com / 403 510 2658
10:15 AM	12:00 PM	Session Chair: Megan Sutton	Session Chair: Jan Kriel	Session Chair: Ibrahim Kodssi
10:15 AIVI	12:00 PIVI	Contact: megan.sutton@acuren.com / 780.909.3689	Contact: jan.kriel@TeamInc.com / 780.237.7452	Contact: ibrahim.kodssi@cenovus.com / p. 403.400.4353
10:15 AM	12:00 PM	Session Judges: Trent Tarleton Contact: trent.tarleton@interpipeline.com / 403.612.4850	Session Judges: Theo Abels Contact: theo.abels@Blu5TC.com / 403.869.1663	Session Judges: John Wolff Contact: john_wolff@transalta.com / 780.916.7861
10:30 AM	11:15 AM	ABST-0376 Touqeer Sohail Challenges of Implementing a Pressure Equipment Integrity	ABST-0400 Lester Stanley Gas Turbine HRSG Outage Inspection Tasks, Examples of Findings & Solutions	ABST-0483 Dan Tompkins Pressure Equipment Overpressure Protection – Overview for Inspectors
11:15 AM	12:00 PM	Program in a Multi-jurisdictional Regulatory Environment ABST-0455 Katherine Jonsson Preventing Corrosion Under Insulation In Piping – Trends after Evaluating Digital Data from Thousands of Piping Circuits	ABST-0370 Matthew Bell Keep the Fire Where it Belongs: Inside the Firetube	ABST-0466 Bruce Stewart Navigating Field Heat Treatment Codes and Standards
12:00 PM	1:00 PM		Lunch	
12:00 PM	1:00 PM	STUDENT POSTER - all day, located between Moose Nook/Beavert Jolene Borrelli Investigation of QW-403.6 Minimum Base Metal Thickness Requirements for Carbon and Low Alloy Steels		
		Baliroom A	Ballroom B	Ballroom C
12:45 PM	3:15 PM	Asset Integrity Management Room Monitor: Mark Stonehouse Contact: mstonehouse@becht.com / 403.604.9332	NDT / New Technologies  Room Monitor: Lauren McAloney  Contact: laurenmcaloney86@gmail.com / 403.815.3981	Regulatory/Codes  Room Monitor: Marc McGill  Contact: atwinspections@telus.net / 780.995.8906
12:45 PM	3:15 PM	Session Chair: Bobby Wright Contact: BWright@becht.com / 281.723.4940	Session Chair: Touqeer Sohail Contact: touqeer.sohail@enbridge.com / 780.680.1515	Session Chair: Hennie Prinsloo Contact: hennie@vasbyt.ca / p. 604.817.7237
12:45 PM	3:15 PM	Session Judges: Rick Marsden Contact: rick.marsden@shaw.ca / 403 651 7141	Session Judges: Theo Abels Contact: theo.abels@Blu5TC.com / 403.869.1663	Session Judges: Jamie Davidson Contact: Jdavidson@amerapex.com / 832.563.6218
1:00 PM	1:45 PM	ABST-0464 Toby Antony Extending Turnaround Frequency of an 80+ year Old Facility from Annual inspection to 3 year frequency	ABST-0372 Steve Strachan IOW Analysis with Installed UT Sensors: How Process Changes Impact Corrosion Rates	ABST-0417 Paul Gorman An Alternate Safety Approach for Reduced Levels of Supervision of Boilers and Heaters in British Columbia
1:45 PM	2:30 PM	ABST-0373 Floyd Baker A new Generation of Asset Integrity Management	ABST-0378 Timothé Falardeau Guided wave ultrasonic testing: applications, limitations, and new developments.	ABST-0443 Shawn Santo What is ASME B31.12?
		ABST-0425	ABST-0374	ABST-0428

2:30 PM	3:15 PM	Dorothy Germain Asset Data Deficiencies – A Cautionary Tale from the Other Side	Improved Imaging of Small Defects and Grainy Material Using Phase Coherence Imaging, a Novel TFM Approach	Donal Heery Qualification of a Non-Standard Piping Component for ASME Pressure Piping Applications (ASME PVP2020-21861)
3:15 PM	3:45 PM		Coffee Break	
3:15 PM	3:45 PM	STUDENT POSTER - all day, located between Moose Nook/Beavert		
		Jolene Borrelli		
		Investigation of QW-403.6 Minimum Base Metal Thickness Requirements for Carbon and Low Alloy Steels		
		Ballroom A	Ballroom B	Ballroom C
		Asset Integrity Management	NDT / New Technologies	Failure Case Study
3:30 PM	5:15 PM	Room Monitor:Bobby Wright	Room Monitor: Nick Marx	Room Monitor: Scott Fong
3.30 1 101	3.131101	Contact: BWright@becht.com / 281.723.4940	Contact: nick@irml.ca /403.318.5010	Contact: scottfong@kasi.ca / (780) 893-7793
3:30 PM	5:15 PM	Session Chair: Ibrahim Kodssi	Session Chair: Rick Marsden	Session Chair: Hennie Prinsloo
3:30 PIVI	2:12 LIAI	Contact: ibrahim.kodssi@cenovus.com / p. 403.400.4353	Contact: rick.marsden@shaw.ca / need	Contact: hennie@vasbyt.ca / p. 604.817.7237
3:30 PM	5:15 PM	Session Judges: Landi Cheng	Session Judges: Theo Abels	Session Judges: John Wolff
3:30 PIVI		Contact: Landi.Cheng@interpipeline.com / 587.475.1153	Contact: theo.abels@Blu5TC.com / 403.869.1663	Contact: john_wolff@transalta.com / 780.916.7861
3:45 PM	4:30 PM	ABST-0393	ABST-0364	ABST-0484
		Daryl Foley	James Parker	Carlo Flores Gil
		Equipment Integrity Management Manuals- What they should	Fully Automated & Integrated Heat Exchanger Tube Cleaning & NDE	Description of the March Lands Books
		contain, why you need them and how they are used.	Technology	Historical Learnings on a Watertube Boiler
		ABST-0365	ABST-0444	ABST-0423
	5:15 PM	Kenny Farrow	Corey Richards	Hans Rautenbach
4:30 PM		The Importance of Pipe Support Inspections for Current Operations and Future Fitness for Service Assessments	Inspection of Gas Storage Tubes with Self-Propelled Solutions	From distress to world-class performance - The story of a 70% reduction in tube failures across a boiler fleet, with associated boiler plant uptime

Wednes	day, Marc	h 1, 2023		
Wednesday	, March 1, 2023	Ballroom A	Ballroom B	Ballroom C
8:00 AM 9:00 AM	10:00 AM	Room Monitor: Nick Marx Contact: nick@irml.ca /403.318.5010	Room Monitor: Jose Arenas Contact: jose.arenas@vysusgroup.com /403.461.1632 KEYNOTE SPEAKER Mr. Mark Black	Room Monitor: Doug Brett Contact: dbrett@secure-energy.com / 403 510 2658
9:00 AIVI	10:00 AIVI		"The Resilience Roadmap™"	
10:00 AM	10:30 AM	Coffee Break		
10:00 AM	10:30 AM	STUDENT POSTER - all day, located between Moose Nook/Beavert Haofei Sun Risk assessment of alloys in brine water under S-CO2 conditions for CCUS-EOR Applications		
		Ballroom A	Ballroom B	Ballroom C
		Asset Integrity Management	NDT / New Technologies	Material Selection / Properties
10:15 AM	12:45 PM	Room Monitor: Landi Cheng	Room Monitor: Trent Tarleton	Room Monitor: Doug Brett
20.207		Contact: Landi.Cheng@interpipeline.com / 587.475.1153	Contact: trent.tarleton@interpipeline.com / 403.612.4850	Contact: dbrett@secure-energy.com / 403 510 2658
10:15 AM	12:45 PM	Session Chair: Carlo Flores Gil	Session Chair: Jan Kriel	Session Chair: Touqeer Sohail
		Contact: carlo.floresgil@nrm.ca/ 403.998.6052	Contact: jan.kriel@TeamInc.com / 780.237.7452	Contact: touqeer.sohail@enbridge.com / 780.680.1515
10:15 AM	12:45 PM	Session Judges: Bastian Zars	Session Judges: Ibrahim Kodssi	Session Judges: John Wolff
		Contact: bastian.zars@vysusgroup.com / p. 403.614.3675	Contact: ibrahim.kodssi@cenovus.com / p. 403.400.4353	Contact: john_wolff@transalta.com / 780.916.7861
	11:15 AM	ABST-0410	ABST-0388	ABST-0377
10:30 AM		Russell Landry  Common Pitfalls in RBI	Geert Bontekoe Finding CUI / Utilizing ILI	Iulian Radu Grade 91 & Grade 92 CSEF Materials for Power Generation - A Practical Perspective
	12:00 PM	ABST-0387	ABST-0458	ABST-0406
		Russ Davis	Cameron Sjerve	Ahmad Raza Khan Rana
11:15 AM		Managing Asset Integrity Risk by Integration of Integrity Operating Windows	Using Laser Scanning Creatively in a Plant Environment	CUI behaviors of carbon steel pipes under mothballed conditions with and without stand-off membranes and low-point drainage
12:00 PM	12:45 PM	ABST-0382	ABST-0426	ABST-0436
		Hassan (Shervin) Sadeghi	Tim Haugen	Gary Coates
		How do corporations evaluate risks when acquiring a new facility? And how can you utilize the technique to assess your own risks?	A Smart Approach to Inspecting Fired Heater and Boiler Coils	Mixing and Matching Stainless Steel Alloys - Which Combinations Will Work and Which Ones Should Be Avoided?
12:45 PM	2:15 PM	Lunch		
12:45 PM	2:15 PM		STUDENT POSTER - all day, located between Moose Nook/Beaver	t
			Haofei Sun	
		Risk assessment of alloys in brine water under S-CO2 conditions for CCUS-EOR Applications		
2:15 PM	5:15 PM	Integrity Challenges Forum		
3:30 PM	4:00 PM	Coffee Break		
3:30 PM	4:00 PM	STUDENT POSTER - all day, located between Moose Nook/Beavert  Haofei Sun  Pick accompany of allow in britan years youngers 502 and things for SSUS FOR Analysis in a		
4:00 PM	5:15 PM	Risk assessment of alloys in brine water under S-CO2 conditions for CCUS-EOR Applications  Integrity Challenges Forum		
7:00 PM	5:15 PIVI 11:00 PM		2 , 2	
7:00 PIVI	11:00 PIVI	Networking Event		

Thursday, Ma	arch 2 2023	Ballroom A	Ballroom B	Ballroom C
marsaay, m	uren 2, 2023	Asset Integrity Management	Failure Case Study	Material Selection / Properties
8:15 AM	10:00 AM	Room Monitor: Jose Arenas	Room Monitor: Mark Palynchuk	Room Monitor: Doug Brett
0.13 AIVI	20.007	Contact: jose.arenas@vysusgroup.com /403.461.1632	Contact: mark@westerninstruments.com / 780.910.4147	Contact: dbrett@secure-energy.com / 403 510 2658
8:15 AM	10:00 AM	Session Chair: Ibrahim Kodssi	Session Chair: Megan Sutton	Session Chair: Theo Abels
		Contact: ibrahim.kodssi@cenovus.com / p. 403.400.4353	Contact: megan.sutton@acuren.com / 780.909.3689	Contact: theo.abels@Blu5TC.com / 403.869.1663
8:15 AM	10:00 AM	Session Judges: Rick Marsden	Session Judges: Carlo Flores Gil	Session Judges: Tyler Letourneau
8:30 AM	9:15 AM	Contact: rick.marsden@shaw.ca / need	Contact: carlo.floresgil@nrm.ca/ 403.998.6052	Contact: tletourneau@capitalpower.com / 832.563.6218
		ABST-0457	ABST-0473	ABST-0392
		Izak Roux	Jorge Perez Fitness for Service assessments using a Fracture Mechanics	Michael Cyca Thermal striping – unique fatigue failure mechanism of piping
		Integrity Management - Lessons Learned	Approach - Case Studies	structures
		ABST-0420	ABST-0452	ABST-0409
		Steve Hall	Sean Croxford	Kimberley Meszaros
9:15 AM	10:00 AM	Managing an IOW Implementation Program from Development to		Analysis and Learnings from Accelerated Wear of a Reducer Spool
		Sustainment	Evaluating PRV Failures, Root Causes, and Mitigation Tactics	Case Study
10:00 AM	10:30 AM		Coffee Break	
			STUDENT POSTER - all day, located between Moose Nook/Beavert	
10:00 AM	10:30 AM		Nicholas Walther	
			Carbon Content Effects on Hydrogen Embrittlement	
10:15 AM	12:00 PM	Room Monitor: Jose Arenas	Room Monitor: Shannon Paquette	Room Monitor: Doug Brett
		Contact: jose.arenas@vysusgroup.com /403.461.1632	Contact: Shannon.paquette@acuren.com /780.265.2902	Contact: dbrett@secure-energy.com / 403 510 2658
10:15 AM	12:00 PM	Session Chair: Ibrahim Kodssi	Session Chair: Bastain Zars	Session Chair: Theo Abels
		Contact: ibrahim.kodssi@cenovus.com / p. 403.400.4353	Contact: bastian.zars@vysusgroup.com / p. 403.614.3675	Contact: theo.abels@Blu5TC.com / 403.869.1663
10:15 AM	12:00 PM	Session Judges: Cody Scheu	Session Judges: John Wolff	Session Judges: Jamie Davidson
		Contact: Cody.scheu@cnrl.com / 403.816.7218	Contact: john_wolff@transalta.com / 780.916.7861	Contact: Jdavidson@amerapex.com / 832.563.6218
	11:15 AM	ABST-0385	ABST-0359	ABST-0358
10:30 AM		Bianca Rode	Scott Fong Considerations for the successful execution of High-Temperature	Dana Cole
		Remaining Life Risk Management of High Temperature Assets	Local Heat Treatments	Steam Separator Foundation Failure Case Study
		ABST-0439	ABST-0416	ABST-0418
	12:00 PM	Peter Shwets	Matthew Yarmuch	Evan Almberg
11:15 AM		Accet Manitesian and Date Cet Overlite and Countries What Date is	David Adaptics of Mandaus Tasks also for Automated Welding of	Thermal modeling of waste heat boiler and heat recovery steam
		Required for Actionable Insights?	s Rapid Adaption of Modern Technologies for Automated Welding of Pressure Equipment	generator steam-side flow deficiencies that lead to long-term
		Required for Actionable misignts:	riessule Equipment	overheat and tube rupture failures
12:00 PM	1:00 PM		Lunch	
42.00.014	4 00 014		STUDENT POSTER - all day, located between Moose Nook/Beavert	
12:00 PM	1:00 PM		Nicholas Walther	
4 00 014	2 22 214		Carbon Content Effects on Hydrogen Embrittlement	
1:00 PM	2:30 PM		Regulator Discussion Panel  Coffee Break	
2:30 PM	3:00 PM		COTTEE Break  STUDENT POSTER - all day, located between Moose Nook/Beavert	
	3:00 PM		Nicholas Walther	
2·30 PM	3.00 DM			
2:30 PM	3:00 PM		Carbon Content Effects on Hydrogen Embrittlement	
2:30 PM	3:00 PM	Ballroom A	Carbon Content Effects on Hydrogen Embrittlement  Ballroom B	Ballroom C
2:30 PM	3:00 PM	Ballroom A	Ballroom B	Ballroom C
2:30 PM 3:00 PM	3:00 PM 5:00 PM	Room Monitor: Nick Marx	Ballroom B Room Monitor: Mark Palynchuk	Room Monitor: Harold Smith
			Ballroom B  Room Monitor: Mark Palynchuk  Contact: mark@westerninstruments.com / 780.910.4147	
		Room Monitor: Nick Marx	Ballroom B Room Monitor: Mark Palynchuk	Room Monitor: Harold Smith